

MACHINE EVALUATION REPORT



| MACHINE DATA | |
|-------------------|------------------|
| Manufacturer | BELL |
| Product Group | DUMPER |
| Model | B20 |
| Serial Number | 40781DVP00080 |
| Year Manufactured | 1997 |
| Year bought | 2007 |
| SMR | 21238 |
| Engine model | |
| Engine S/N | ML010915A104138C |

| GENERAL INFORMATION | |
|---------------------------|---------------|
| Date of inspection | 22-Jul-09 |
| Name of inspector | GIEP DE KLERK |
| Customer name | |
| Contact | |
| Location | POTCHEFSTROOM |
| Type of usage / applicat. | |
| Expected entry date | |
| Expected SMR | |

| MACHINE MAIN SPECS | |
|------------------------------|------------|
| Body Type | DUMPER |
| Body Capacity m ³ | 20T |
| Body Extension mm | |
| Cab: | STEEL |
| Tire Size & type | 20.5 X 25 |
| Tire Brand | YOKOHAMA'S |
| Dump Trucks Type | |

| STAR RATING | | | | | |
|-----------------------------|---------|---------|---------|--------|-------|
| EX | GOOD | FAIR | AV | POOR | |
| XXXXX | XXXX | XXX | XX | X | XXXX |
| 90% + | 70 - 90 | 50 - 70 | 40 - 50 | < 40 % | 73.21 |
| MAIN COMPONENT CONDITION | | | | | |
| Exterior | | | | | 90 |
| Cab | | | | | 90 |
| Right Front Tire | | | | | 80 |
| Left Front Tire | | | | | 50 |
| Right Rear Tire | | | | | 10 |
| Left Rear Tire | | | | | |
| Right Mid Tire | | | | | 20 |
| Left Mid Tire | | | | | 10 |
| Under Garriage Left | | | | | |
| Under Garriage Right | | | | | |
| Engine Performance | | | | | 100 |
| Electric System | | | | | 100 |
| Hydraulic Performance | | | | | 100 |
| Working Attachments | | | | | 80 |
| Dumper assy | | | | | 90 |
| Drive Train | | | | | 100 |
| Safety Items & Compliance | | | | | 70 |
| Main Frame | | | | | 90 |
| Steering Cylinder & Linkage | | | | | 100 |
| Paint Condition | | | | | 90 |
| Heater / Air Conditioner | | | | | 90 |
| Warning Lights | | | | | 90 |
| Transmission | | | | | 100 |
| Torque converter | | | | | 100 |
| Final Drives | | | | | 100 |
| Service Brakes | | | | | 100 |
| Parking Brake | | | | | 100 |
| Guages | | | | | 100 |

| Plant | | | | | |
|-------|---|---|---|---|---|
| P | S | 0 | 0 | 3 | 7 |

| COMPLIANCES | YES | NO |
|----------------|-----|----|
| O & M Manual | √ | |
| CE Plate | | √ |
| CE Certificate | | √ |
| ROPS Plate | | √ |
| Others | | √ |

| SERVICE RECORDS | YES | NO |
|---------------------------|-----|----|
| Mach. History | √ | |
| Good state of maintenance | √ | |

| CURRENT EVALUATION | |
|----------------------|----|
| Mach. Age (Years) | 12 |
| Avg hrs / year (Hrs) | |

| GENERAL REMARKS: | |
|------------------------|--|
| Overhauled: | |
| Engine | |
| Transmission | |
| Hydraulic Cylinders | |
| Propshafts | |
| Radiator and Coolers | |
| Brakes and Boosters | |
| Hub Seals and Bearings | |



| | | | |
|--|--|---------------------------|--------------|
| www.alsplantsales.co.za | Phone Johan: 082 450 0451 / 018 290 8070 | OUR NET PRICE (VAT EXCL.) | R 600,000.00 |
|--|--|---------------------------|--------------|

Whilst every effort has been made by ALS Plant Sales to ensure the accuracy of the information/images displayed. The availability of products offered or accuracy cannot be guaranteed. Prices are subject to change without prior notice. Pictures are only a representation of products and may not be an exact resemblance.